




**Model # 78620**

**SUBARU BALL JOINT PULLER**



**FOR DIFFICULT TO REMOVE,  
SEIZED, RUSTED AND/OR CORRODED  
BOLT-IN SUBARU BALL JOINTS**



**SALES AND MARKETING**  
1230 Santa Anita Avenue, Suite E  
South El Monte, CA 91733  
**Phone: (800) 221-9705**  
**USA Toll Free**  
Fax: (877) 318-2194  
Phone: (626) 228-3170  
Fax: (626) 228-3124

372 Old US Highway  
52 South  
Mount Airy, NC 27030

Model	Applications
<b>78620</b>	<b>Subaru Baja 2003+, Forester 1998+, Impreza 1993+, Legacy 1990+, Outback 2000+ and more</b>

**DESIGNED FOR EASY USE WITH VEHICLE  
ON JACK STANDS USING A DEEP 24MM  
SOCKET AND IMPACT OR HAND WRENCH**

**OR USE INCLUDED 5/8-18 THREAD  
ADAPTER WITH ANY COMMON SLIDE  
HAMMER**

**Astro Pneumatic  
Tool Company**

E-mail : [astrotools@astrotools.com](mailto:astrotools@astrotools.com)  
WEBSITE : [www.astrotools.com](http://www.astrotools.com)



**UNDERCAR KIT**

